


Installing Cutting Master 3 <Windows>


1. Double-click the icon of the downloaded software installer to start installation.




2. The [Cutting Master 3 Setup] wizard is starting and [Welcome] screen appears. Click the "Next" button.




3. The [Select Installation Folder] screen appears. Check the displayed folder and location. If the folder and location need to change, select it using the "Browse" button. Then click the "Next" button.



4. The [Ready to Install] screen appears. Click the "Install" button for starting the installation of software.





5. When the [Completing] screen appears, click the "Finish" button.
The installation of Cutting Master 3 is completed.

